


NOW CERTIFIED AND AVAILABLE

SKCP 2456-3



SKCP 2456-3

- No lubrication or maintenance
- Long service life
- Fail-safe
- Ease of inspection
- Repairable
- Competitive price

Having received necessary FAA certification, MBB has now included the Kamatics **KAFLEX** driveshaft in its List of Material as an interchangeable replacement for the existing driveshaft, part no. 19E146-1B. Kamatics has been authorized by MBB to offer this as a direct sale to operations of BO-105 helicopters.

The BO-105 **KAFLEX** driveshafts, Kamatics part no. SKCP 2456-3, incorporates the same design and construction utilized in over 20,000 helicopter driveshafts presently in operation worldwide. The design has been successfully proven in over a decade of service. Helicopters utilizing **KAFLEX** driveshafts include the Bell OH-58 "KIOWA," UH-1 "HUEY," AH-1 "COBRA," 206B, 206L, 206L4, 407, McDonnell Douglas MD500 series, and MD600N helicopters.

KAFLEX - Outstanding Performance and Proven!

KAFlex Driveshafts

Products of

Kamatics Corporation

KAMAN

